

Drain Survey mode performed in error.

Symptoms:

Drain line is present in the elevation data path.

Possible cause:

T3C user has recorded in Drain survey mode instead of Field survey mode as intended. Drain lines are in a swath pattern across the field.

Solutions:

If a user does not wish to resurvey in Field survey mode, they can:

- 1. Delete drain line T3RRA Design (T3RRA Cutta owners only).**
 - 1. Load the project into T3RRA Design**
 - 2. Delete the drain line on the Guide tab**
 - 3. Export a control file for T3C**
- 2. In Collect step of Wizard:**
 - 1. Export data as CSV file**
 - 2. Import CSV file into T3RRA Cutta v2.**

