T3RRA

Imported SWP+ ditch track names are too long.

March 2025

Contents

Imported SWP+ ditch track names are too long.

Imported SWP+ ditch track names are too long.

Symptoms:
After importing SWP+ ditch tracks, you see that their assigned names are too long and cover most of the surface.

Cause:
Previously assigned names are imported along with ditch tracks.

Solutions:
Return to the Surface step and use the Edit Drains button to rename.



Click on the pencil and paper icon, rename drain, choose Ok, then Close.



