

10.3 | Hydraulic Control Issues

Issue	Possible Cause	Recommended Action
Automatic Control disengages during operation	Hydraulic response outside configured limits	Verify hydraulic tuning and response stability
Automatic Control performance inconsistent	Incorrect implement profile selected	Verify correct implement configuration within Level COMMAND