

# Exporting a T3RRA Cutta (\*.tci) control file

This is our preferred control file format. It works very well with T3RRA Cutta, funnily enough.

1. Open the Export window as described [here](#).
2. Select T3RRA Cutta (\*.tci) from the Export Type list.
3. Remove any excess surfaces from the list in the center.
4. For the drains and linework, choose whether T3RRA Cutta treats them as just linework or control lines (i.e. drains). Treating them as drains will enable profile views for them in T3RRA Cutta.
5. Click the [Export] button and choose a location and file name.

