

# Dual GPS scraper is not level.

## Symptoms:

**When using two GPS receivers in a side-by-side configuration on a single scraper, one side of the scraper is consistently lower than the other side.**

## Cause:

**One GPS is mounted lower than the other, or Implement GPS Receiver Offsets are incorrectly entered.**

## Solution:

**Select Controller Setup softkey > Profile tab > GPS Offsets Edit button. Enter the correct GPS height offsets.**

