

Implement is offset a large amount after 'zeroing'

Symptom:

Your implement is offset by a large amount when you zero before implementing.

Possible causes:

1. A value has been entered into the Blade clearance causing the zeroed amount to be higher than normal.

Solutions:
