

Troubleshooting performance.

Symptoms:

- **Implement responds too slowly to changes in grade**
- **Blade fails to hold grade**
- **Unexpected shifts in blade elevation occur**
- **Implement appears not to respond to commands**
- **Cross slope not working**
- **Cross slope behaving unexpectedly**

Cause:

“Performance” is a subjective term. There are many ways in which a system can suffer poor “performance”. Thus there are also many causes for this. The exact cause will differ with the type of performance degradation present. Specific types will be discussed further in other parts of this document. However the below advice is almost always relevant.

Solutions:

The first step when diagnosing any performance issue is to disconnect the T3RRA software and to test iGrade *in isolation*. Only once you have confirmed that iGrade is working properly, you can then start to troubleshoot the T3RRA software. Place iGrade in Plane Control or Grade Control and establish that it is performing

as expected. If it is, reconnect the T3RRA software and continue with other solutions in this troubleshooting guide. If it isn't please consult your John Deere dealer.
