

DXF import failure

March 2025

Contents

DXF import failure


DXF import failure

Symptoms:

DXF file import is unsuccessful. Error message "DXF linework import has failed: Object reference not set to an instance of an object" when importing DXF into T3D.

Cause:

DWG saved as R12/LT2 DXF.



Solutions:

DWG saved as 2013 DXF.