


The Implementation Screen

When you begin implementation of your design, the display will show a cut/fill map as well as tools to assist in the implementation of the design.



Screen features of interest include:

1. Setting Zero button.
2. Cross-slope nudge control buttons.
3. Vertical blade shift control buttons.
4. Cut/Fill Information & horizontal colour bar.
5. Progress Indicator.
6. On-Grade Indicator.

- 7. Blade and Tractor Indicators.**
 - 8. Map display.**
 - 9. Drain profile and cross section.**
-